GOT TO FIRE IT'S NO


USE! I'VE LOST THE FORCE!

A WEAK MGS BATTERY MAKES FOR A NO-GO TOW. TO KEEP THE TOW ON ITS TOES, GOOD BATTERY PM IS A MUST. AND IT BEGINS WITH YOU, REPAIRMEN.




very battery should be charged at least every 30 days. To keep track, write the charging date on a piece of tape and stick it to the top of the battery.

If you charge correctly but the battery still doesn't have much power, dirty connectors could be the problem. So, clean both battery and charger connectors with denatured alcohol and a swab made from a clean cloth and a stick. Then discharge and recharge again.



Sometimes chargers just plain go bad. If three or more batteries fail to take a charge, have support check the charger.

When the TOW 2 is back home, store batteries in a dry, cool place. Heat and humidity weaken batteries.



PS 588

BATTERY

PM WILL

CONNECT

YOU TO

THE

FORCE!

Make sure each fastener has a retaining clip. Without a clip, the fastener will disappear. If the clip is missing, get your armorer to lockwire the fastener. That actually works better than the clip.

Operators, make sure each battery

has at least four fasteners. If it doesn't.

the battery can't be secured and the

MGS will start showing faults.

with NSN 5325-01-148-8601.



At least four wing fasteners?

PS 588 42 **NOV 01**